





PLUMB / LEVEL




Digital level to BE used.

Assess to 1 Decimal Place.






Angles.
Point of Assessment




2.5 Hours

DIGITAL
ANGLE
FINDER
MUST BE
USED.
ASSES TO
1 Decimal
Place.






SOLDERING ASSESSMENT POINTS 1-7




Only look at side of fitting identified.

e.g. a tee has three potential assessment points,





2.5 Hours





DIMENSION ASSESSMENT POINTS



Measurements
to be taken
approx. to identified
location.

